

COOK COUNTY LANDFILL
1200 S HUTCHINSON AVE
ADEL 31620-5218

CUSTOMER NO.	ESTIMATE NO.	DATE	CONTACT
804513	113269	7/20/2022	DANIEL BARBER
PHONE NO.	FAX NO.	EMAIL	
2298962296			
MODEL	MAKE	SERIAL NO.	
615C	AA	9XG01302	
UNIT NO.	WO NO.	P.O. NO.	
ESTIMATE DESCRIPTION:		ADDITIONALS	

SEGMENT: 01 REPLACE TRANSMISSION SPEED SENSOR (510 3175)

Part Number	Description	Qty	Unit Price	PartDiscount	Discount %	Ext Price
3181181	SENSOR GP	1	153.19	0.0000	0.00	153.19

Total Estimated Parts: 153.19

Item Number	Description	Qty	Unit Price	Discount %	Ext Price
SHP	REPLACE TRANSMISSION SPEED SENSOR	1	156.00	0.00	156.00

Total Estimated Labor: 156.00

Segment 01 Total: 309.19

SEGMENT: 02 REPAIR HOSES& LINES (023 7554)

Part Number	Description	Qty	Unit Price	PartDiscount	Discount %	Ext Price
8X1143	CLAMP	2	20.50	0.0000	0.00	41.00
2552287	HOSE	1	132.02	0.0000	0.00	132.02
2T2100	HOSE A	1	117.86	0.0000	0.00	117.86
2T3779	HOSE AS	1	136.94	0.0000	0.00	136.94
2T2093	HOSE A	1	149.76	0.0000	0.00	149.76
423-1980	HOSE-BULK	143	0.42	0.0000	0.00	60.06

Total Estimated Parts: 637.64

Item Number	Description	Qty	Unit Price	Discount %	Ext Price
SHP	REPLACE HOSES AND LINES	2	156.00	0.00	312.00

Total Estimated Labor: 312.00

Segment 02 Total: 949.64

SEGMENT: 03

REPAIR STEERING CYLINDER MOUNTING (023 4303 MT)

Part Number	Description	Qty	Unit Price	PartDiscount	Discount %	Ext Price
8T8915	BOLT	2	1.76	0.0000	0.00	3.52
5P1075	WASHER	2	0.73	0.0000	0.00	1.46
1S1445	PLATE	1	22.62	0.0000	0.00	22.62
8X1146	SPACER	1	29.62	0.0000	0.00	29.62
8X1143	CLAMP	2	20.50	0.0000	0.00	41.00

Total Estimated Parts: 98.22

Item Number	Description	Qty	Unit Price	Discount %	Ext Price
SHP	REMOVE BROKEN BOLTS	2	156.00	0.00	312.00
SHP	REPAIR STEERING CYLINDERS PIN	3	156.00	0.00	468.00

Total Estimated Labor: 780.00**Segment 03 Total:** 878.22**SEGMENT: 04**

REPAIR FINAL DRIVE & BRAKE WHEEL STUD(S) (023 4001 SD)

Part Number	Description	Qty	Unit Price	PartDiscount	Discount %	Ext Price
1A1135	CAPSCREW	1	2.76	0.0000	0.00	2.76

Total Estimated Parts: 2.76

Item Number	Description	Qty	Unit Price	Discount %	Ext Price
FLD	CLEAN HOLE AND INSTALL THE BOLT	0.5	156.00	0.00	78.00

Total Estimated Labor: 78.00**Segment 04 Total:** 80.76**SEGMENT: 06**

REPAIR FUEL SYSTEM (023 1250)

Part Number	Description	Qty	Unit Price	PartDiscount	Discount %	Ext Price
1044253	LINE AS	1	156.54	0.0000	0.00	156.54
1044254	LINE AS	1	155.08	0.0000	0.00	155.08
2T1759	TUBE A	1	330.15	0.0000	0.00	330.15
2T1764	TUBE A	1	333.15	0.0000	0.00	333.15
2T2064	TUBE A	1	138.70	0.0000	0.00	138.70
2T2527	TUBE A	1	287.22	0.0000	0.00	287.22
2T2528	TUBE A	1	258.45	0.0000	0.00	258.45
2T2529	TUBE A	1	298.22	0.0000	0.00	298.22
2T2728	TUBE A	1	212.75	0.0000	0.00	212.75
3J1907	SEAL	3	1.29	0.0000	0.00	3.87
3J7354	SEAL-O-RING	1	1.16	0.0000	0.00	1.16
3K0360	SEAL-O-RING	2	1.46	0.0000	0.00	2.92
4P9382	LINE AS	1	156.54	0.0000	0.00	156.54
6V8397	SEAL	24	1.31	0.0000	0.00	31.44
3S2093	TIE	6	0.26	0.0000	0.00	1.56

4P9381	LINE AS	1	156.56	0.0000	0.00	156.56
4P9385	LINE AS	1	155.08	0.0000	0.00	155.08
4P9386	LINE AS	1	153.67	0.0000	0.00	153.67

Total Estimated Parts: 2,833.06

Item Number	Description	Qty	Unit Price	Discount %	Ext Price
SHP	FLUSH/ REPLACE FUEL TANK AND LINES	10	156.00	0.00	1,560.00

Total Estimated Labor: 1,560.00

Item Number	Description	Qty	Unit Price	Discount %	Ext Price
MISC	MISC	1	75.00	0.00	75.00

Total Estimated Misc: 75.00

Segment 06 Total: 4,468.06

SEGMENT: 07 REPAIR ENGINE FOR LEAKS (023 1000 FKK)

DOES NOT INCLUDE ANYTHING FOUND BAD UPON
DISASSEMBLY

Part Number	Description	Qty	Unit Price	PartDiscount	Discount %	Ext Price
0L1352	CAP SCREW	3	1.47	0.0000	0.00	4.41
0T0573	CAP SCREW	5	1.29	0.0000	0.00	6.45
165-3929	BOLT-HEX HEA	18	0.81	0.0000	0.00	14.58
1694199	GASKET-OIL	1	38.14	0.0000	0.00	38.14
1694200	GASKET	1	34.81	0.0000	0.00	34.81
3B1915	BOLT	18	0.70	0.0000	0.00	12.60
5M2894	WASHER	44	0.44	0.0000	0.00	19.36
5P0076	BOLT 12 PT H	2	5.39	0.0000	0.00	10.78
6N7887	GASKET	1	9.42	0.0000	0.00	9.42
8N6854	GASKET-OIL	1	4.53	0.0000	0.00	4.53

Total Estimated Parts: 155.08

Item Number	Description	Qty	Unit Price	Discount %	Ext Price
SHP	ENGINE HAS MULTIPLE OIL LEAKS. REPLCE BOTH OIL PAN ENGINE OIL FILLER GASKET. ALSO REPLCE THE O-RINGS GASKETS AS THEY ARE BOTH LEAKING. REPLACE THE ON A HYDRAULIC HOSE THAT IS LEAKING ONTO THE	7	156.00	0.00	1,092.00

Total Estimated Labor: 1,092.00

Item Number	Description	Qty	Unit Price	Discount %	Ext Price
MISC	MISC	1	75.00	0.00	75.00

Total Estimated Misc: 75.00

Segment 07 Total: 1,322.08

SEGMENT: 08 REPAIR AIR CONDITIONER (023 7320)

DOES NOT INCLUDE ANYTHING FOUND BAD UPON
DISASSEMBLY

Part Number	Description	Qty	Unit Price	PartDiscount	Discount %	Ext Price
1168653	POTENTIO MET	1	261.03	0.0000	0.00	261.03
5D1026	CLAMP HOSE	4	2.29	0.0000	0.00	9.16
6B1628	ADAPTER	1	8.21	0.0000	0.00	8.21
8F8151	COCK	2	18.49	0.0000	0.00	36.98
9G2265	CLIP	1	2.97	0.0000	0.00	2.97

Total Estimated Parts: 318.35

Item Number	Description	Qty	Unit Price	Discount %	Ext Price
SHP	THE A/C CONTROL SWITH IN THE CAB IS NOT WORKING. REPLACE THE A/C TEMPATURE CONTROL SWITH IN THE CAB. REPLACE VALVES	4	156.00	0.00	624.00

Total Estimated Labor: 624.00

Item Number	Description	Qty	Unit Price	Discount %	Ext Price
MISC	MISC	1	75.00	0.00	75.00

Total Estimated Misc: 75.00

Segment 08 Total: 1,017.35

Total Segments: 9,025.30

SUB TOTAL (BEFORE TAXES) 9,025.30

-This estimate will expire 30 days from the estimate date.
-Price excludes Freight Charges, Operating Supplies/EPA Fees and Overtime.
-Terms: Net 30
-Sales Taxes where applicable are not included with the above prices.

ESTIMATED REPAIR TIME: _____ *from start date*
"The signature is an authorization to proceed with the required repair work as described within the quote"

Issued PO#: _____ **Authorized Name:** _____ **Please Print**

Date: ____/____/____.

Signature

Any questions? Please call Roger Dickens at Office: 904-252-8516 Mobile: 904-252-8516 Fax: Branch:
