

IN SERVICE TO SERVE YOU

Ten-8 Fire & Safety Equip of GA 1591 Collier Road Forsyth, GA 31029

Phone No.

1-478-994-3235

Fax No.

1-478-994-6458

## COOK COUNTY COMMISSIONERS

1200 S. HUTCHINSON AVE

ADEL, GA 31620

Phone No.:

Email:

Service Estimate Page 1

GQ2565

No.

Pending

Status

02/14/19

Order Date Order Time

11:09:27 AM

0.00

0.00

3,740.31

Contract No.

Invoice To: COOK COUNTY COMMISSIONERS

PO Number

Equip ld: 2097

1K9AF4288RN058037

Veh. Miles: 0 Veh. Hrs.: 0

Approved:

## Vehicle Services

Complaint 1:

REPAIR VACUM LEAAKS

Fault

UNIT WOULD NOT PASS DRY VACUM TEST DURNING PUMP TEST

Resolution

REBULD FOLLOWING VALVES

DISCHARGES 1,2,3,4, REAR DISCHARGE, DECK GUN, TANK FILL, TANK TO PUMP,

DRIVER AND PASS SIDE INLET 2.5 AND UPPER SPEEDLAY

TOTAL OF 11 BALL VALVES

Service Lines	s		04	Unit Price	UoM	Amount	Disc. Amt.	Net Amount
Type	No.	Description	Qty.	Office			0.00	215,66
Item	AKR-8905	VALVE KIT 2.0", COMPOSITE	2.00	107.82857	EACH	215.66	0.00	210.00
nem .	71111	BALL	100 00571	EACH	655.72	0.00	655.72	
Item	AKR-8906	VALVE KIT 2.5"	6.00	109.28571			0.00	467.75
	640 (100) 1000 (100)	VALVE KIT 3.0"	3.00	155.91429	EACH	467.75		
Item	AKR-8907		1.00	56.00	EACH	56.00	0.00	56.00
Resource	FRT	FREIGHT CHARGES		65.00	HOUR	130.00	0.00	130.00
Resource	STONE	MOBILE SERVICE CHARGE	2.00		2070-0-200000	1690.00	0.00	1,690.00
	STONE	PATRICK STONE	13.00	130,00	HOUR			135.20
Resource	STONE	SHOP SUPPLY FEE	1.00	135.20	EACH	135.20	0.00	
G/L	30500	SHOP SUPPLIFIE	Total			3350.33	0.00	3,350.33
		و الله الله الله الله الله الله الله الل						****

EXTRA DIAGNOSTIC TIME FROM PUMP SERVICE Complaint 2:

Date : \_\_\_\_\_

Service Line	s		Otre	Unit Price	UoM	Amount	Disc. Amt.	Net Amount
Туре	No.	Description	Qty. 3.00	130.00	HOUR	390.00	0.00	390.00
Resource	LABUR	LABOR	т.	ital	water south	390.00	0.00	390.00
			Total					
	the state that any and got that had see the table to see and the se	· · · · · · · · · · · · · · · · · · ·		MATEC ADE	Total	Amount	\$	3,740.31

THIS IS AN ESTIMATE, NOT A CONTRACT AND IS VALID FOR 30 CALENDAR DAYS. ESTIMATES ARE PROVIDED ON A BEST ENDEAVORS BASIS ONLY. WORK WILL BE CHARGED BASED UPON THE PRICE OF PARTS PROVIDED BY TEN-8 FIRE EQUIPMENT PLUS LABOR. IF THERE IS ANY UNFORESEEN WORK DIRECTLY RELATED TO THE REPAIRS ON THE ESTIMATE. THE CUSTOMER WILL BE CONTACTED FOR AUTHORIZATION TO COMPLETE THE ADDITIONAL WORK. IF THE ADDITIONAL WORK IS DECLINED THE CUSTOMER IS STILL LIABLE FOR ANY WORK COMPLETED. BY SIGNING BELOW YOU AUTHORIZE TEN-8 EQUIPMENT TO PERFORM THE REPAIRS DETAILED IN THE ESTIMATE ABOVE. **Total Amount** \$ \$ Discount \$ Taxes **Balance Due** THE ESTIMATE ABOVE.

Confirm Info	***	Signature	<b>:</b> ;	4		
Commin me						

EN-8 Equipment of Control Service Repair Ticket **Customer Contact:** Customer Name: Cook County - Pine Valley

> Date: 2/5/2019

Timmy Guthrie PO#: CP / W / I Travel Hours: Customer Pay Travel Mileage: na 1994 Mileage: Service Ticket# Tech. Ticket # 113813 Eng. Hrs Technician GSV13888 Stone 2986 11396

. ol SS.
...direr Raud
...orych., GA.31129
PBONE: 1-478-994-5428
FAX: 1-478-994-6458
www.neidline.com Job # or VIN Checked primer operation - ok. Performed dry vacuum test - failed due to leaks. Found that  $|\mathsf{Pump}$  service: Drained and changed oil in t-case, lubricated driveline and valve linkages. Repair Operation #1 Description of Work packing was leaking badly, adjusted pump packing to specs. Packing felt very hard and may valve, 2"akr tank fill (labeled incorrectly), 3"akr tank to pump, 2.5"d/s aux inlet, 2.5"akr disch need replacing in the near future. Found to be leaking: 2.5"akr p/s aux inlet, 3"akr deck gun cooler line leaking water badly - tightened and tested - ok. Also found that somewhere along 1, 2, 3, 4, 2.5"akr rear disch, 2"akr upper speedlay valves. Also found pump transmission | ank. The ank will need to be removed at our Forsyth facillity for repair. 1.50 hrs were added the forward end at the top of the booster tank there is a split that will leak water from the due to extensive diagnosis time. Perform NFPA pump test: failed dry vacuum test. Passed pump test. Repair Operation #2 Description of Work Truck will not hold water: Repair Operation #3 Description of Work Repair Operation #4 Description of Work 2097 Contact Phone #: Veh. Make: 229-560-0388 KME Veh. Model: Eng 22 Oty. Veh. Yr: ∞ Part # quarts Parts and Material Used Part Description 80W-90 gear oil

Repair Operation #5 Description of Work

_	0 -	-1	-	0. 5	= :	~		
	herb or els	Teardown estimate - I understand that my verifice will be necessary mat	0	signature will indicate your estimate selection.	loss than the estimate, but will not exceed the estimate without your permission.	ou ar		
	y aut ewhe	nwo		ure v	an th	e en		
	hori ere,	esti		<u> </u>	9	title		
	ize th	mate	١	ndic	stim	dto		
	ne ak		١	ate y	te, l	a pri		
	ove	indei	1	our	but v	ce es		
	repa se of	stan	١	stim	ìll n	tima		
	ir wo	מנה		ate	ot ex	te fo		
	ng a			selec	ceed	r the		
	/ pr	1		tion.	the	repa		
	or ins		2		estim	airs y		
	pecti		1		nate v	ou ha		
	on. A		reas		VITNO	ve al		
	n exp	†	semb		ut yo	ייייייייייייייייייייייייייייייייייייייי		
	press	nece	oled v		מו	izeu.		
	mech	sarv	vithir			mis	140	
	nanic	mate	ĺ			ion.	iena:	
	s lien	rial,				Your	ma	
$\ $	is he	and t	days				be	
$\ $	reby	herby	of th	<u>w</u>	!	3	1.	
	ackno	gran	e date	don		أوعوا	requ	
	l herby authorize the above repair work to be done above, small method acknowledged on above venicle to secure the small print and or inspection. An express mechanics lien is hereby acknowledged on above venicle to secure the small print and or inspection. An express mechanics lien is hereby acknowledged on above venicle to secure the small print and or inspection.	you	days of the date shown it i choose not to demonstrate	3. I do not want an estilliace.		proc	The repairs be 1. I request an estimate in writing before you begin repairs.	
	lged o	and/o	ND II	nt an		eed v	estir	
	on ab	or you	CITO	esu	-	vith r	nate	
	ove v	ur em	250	late.	1	epair	in wr	
	enici	ploy	2	3		s, bu	iting	
	0 0	ees p	1	d tine		tcall	befor	
1	ecni	ermis		rize		me b	e you	
	:	sion		the s		efore	ı beg	
3		to op	1	ervice		cont	in rep	
2		erate		reco		inuin	airs.	
3		the	1	mme		g if th		
崩		/ehicle		nded		ie prio		
		e ner	1			e WII		
SE B		. em as				before continuing if the price will exceed 2		
8		50				, na	2	
ND		2	2					
OUR			ctro					
6			Ptc h					
OF ANY OTHER CAUSE BEYOND OUR CONTROL.		Teardown estimate - I understand that my vermice will be necessary material, and herby grant you and/or your employees permission to operate the vehicle nerein described with the necessary material, and herby grant you and/or your employees permission to operate the vehicle nerein described with the necessary material, and herby grant you and/or your employees permission to operate the vehicle nerein described with the necessary material, and herby grant you and/or your employees permission to operate the vehicle nerein described with the necessary material, and herby grant you and/or your employees permission to operate the vehicle nerein described with the necessary material.	ighwa					
ĭ			SVE.			,		
					- 1			