

Request for Board of Commissioners' Action

From: Faye Hughes, County Administrator Date: 1/28/2020

Subject: Landfill Dirt Pan Item Number: VII-A

Below are the warranty specifications the Board asked Daniel Barber to get from Yancey concerning the propose dirt pan for the landfill. The used dirt pan has 5298 hours on it. There are three (3) different warranty prices. The CAT Certified Rebuild (CCR) is the same for all three proposals. The only difference is the Length of time and the price. The original proposal was \$451,094.72 with 3 Year 5,000 Hour Powertrain and Hydraulic Warranty. The second proposal is 4 Year 8,000 Hour Powertrain and Hydraulic Warranty \$459,434.72 and the third is 5 Years 10,000 Hour Powertrain and Hydrailic Warranty \$472,954.72. Please remember this is not eligible for a buy back.

SEGMENT: 01 PERFORM CERTIFIED POWERTRAIN

- Disassemble/Assemble Machine
- Remanufactured Engine - Including Alternator/Starter
- Recondition/Rebuild Transmission/Torque Converter - Including Transmission Pump and Cooler
- Recondition Axle Assembly – Differential, Finals Drives, and Brakes
- Recondition Radiator – Hoses, Clamps, and Lines
- New Powertrain ECM

SEGMENT: 02 REBUILD HYDRAULIC SYSTEM

- New/Remanufactured Pumps and Motors – Including Steering and Braking When Applicable
- Recondition All Hydraulic Valves – Including Main Control Valve
- All New Hydraulic Hoses and Lines
- Reseal All Cylinders
- Recondition Hydraulic Tank

SEGMENT: 03 RECONDITION OPERATOR STATION

- Recondition Heat/AC
- New Seat Group
- New Insulation/Liners
- Recondition Panels and Controls

SEGMENT: 04 REBUILD ELECTRIC SYSTEM

- All New Machine Harnesses
- New Batteries and Wiring Groups
- New Lighting

SEGMENT: 06 PAINT MACHINE

- Paint and Decals for 615C

SEGMENT: 07 ADD-ONS SCRAPER

SEGMENT: 08 ADD PRODUCT UPDATE PROGRAM

- A New Yoke Assembly Improves Reliability. Effective With 9XG01714-99999. Required On 9XG00001-01713.
- An Update to the Hydraulic Oil Lines Group Improves Field Operation.
- New Tube Now Used in Hydraulic Lines Resists Splitting.
- A New Pilot Valve for the Elevator is Now Available on Certain Wheel Tractor-Scrapers.
- Install Product Link System

Motion made by _____ Second made by _____
Any discussion: _____

Votes _____ yes _____ no Motion carried/ failed